

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY  
T 49N R 9W

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 3-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/25/71

WITNESSES TO CORNER..... 8" J. Pine S09°W 18.3'



10" J. Pine N26 1/2°W 32.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in south wheel rut of E-W fireline.

Corner re-established midway and on line bet. two Sec. Cors.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 12/17/71  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing ✓

R 4047  
Rev. 10/68