

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Center Corner, Section 24

CORNER MONUMENT 1" x 48" iron pipe and wood post.

DATE MONUMENT PLACED AND WITNESSED 8/28/58

WITNESSES TO CORNER..... 10" W. Pine (C BT) N27°E 39 links



8" W. Pine (C BT) West 25½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in marsh and 90 links east of road.

This corner placed at intersection of N.-S. and E.-W. quarter lines, while make a Section sub-division survey.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 1-20-71