

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER North 1/16 Corner, Sec. 24

CORNER MONUMENT 1" x 48" iron pipe and wood post

DATE MONUMENT PLACED AND WITNESSED 8-28-58

WITNESSES TO CORNER..... 7" Red Pine S48°E 46 links



14" Red Pine S64°W 57 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed on line and midway bet.  $\frac{1}{4}$  corner to north and center of section to south, while sub-dividing this section.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler REGISTERED LAND SURVEYOR DATE 1-21-71