

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 9. W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section corner between Sections 4, 5, 8 and 9. . .

DESCRIPTION OF CORNER MONUMENT 2" Iron Pipe buried in intersection of
N-S-E-W firelanes.

WITNESSES TO CORNER 9" Jack Pine S 55 E 38 Links (NBT)

6" Jack Pine N 30 E 60 1/2 Links (S 4 NBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was re-witnessed as set by Marcus Schaaf, Reg. Surveyor. Found 2" Iron Pipe with two Spruce Pine B.T.'s. Bearing N 46 1/2 W, 97 Links, down, but in fair condition, and S 61 E, 74 Links, down and in peer condition.

Shown by B. McTiver, District Forester.

Corner was placed and witnessed on 27 May 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6-8-59
REGISTERED LAND SURVEYOR