

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49-50 N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between 3-34

CORNER MONUMENT 2" Iron Pipe buried in center of E-W Fire line.

DATE MONUMENT PLACED AND WITNESSED 7-25-61

WITNESSES TO CORNER..... 8" Jack Pine (1/4 S NBT) S 50° W 28 links



8" Jack Pine (1/4 S NBT) North 20 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by Marcus Schaaf, Registered Land Surveyor.
Found 2" Iron Pipe in place.
No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 30, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler