MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_49_ NR__9 W__

			L	10 <u>e</u>	COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sec	2.15_23-24	
DESCRIPTION	OF	CORNER	MONUMENT1" pipe 1	dth 4" bress	Ç2 ğ
WITTNESSES	то	CORNER	_ 15"_Red_Pine 71/1	N 25° E 4 S NBT"	<u> Vījā jinka</u>
			14" Red Pine	S 35° E 4 S NBT	80 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner as set by Marcus Schaff, Reg. Surveyor.

Found 2" iron pipe in place.

Found site of two Tamarack Stumps in proper position.

1/4 corner lies in swamp.

Corner placed and witnessed December 5, 1957.

SURVEYORS SEAL

SIGNED Selly Duckles DATE 12/19/57