

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..49. NR. 9 W. . . .

-----Luce----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 9-16

DESCRIPTION OF CORNER MONUMENT 2" Iron Pipe buried in E. and W. Firelane

WITNESSES TO CORNER 10" Jackpine (1/4S NBT) N 53° E 3/4 Links

9" Jackpine (1/4S NBT) S 22° E 21 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Re-witnessed Corner as set by Marcus Schaaf, Reg. Surveyor. Found 2"
Iron Pipe in place witnessed by Pits and Mounds. No evidence of original witnesses.

Corner lies in E. & W. Firelanes.

Shown by B. McTiver, District Forester.

Corner was re-witnessed May 29, 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 12/3/58
REGISTERED LAND SURVEYOR