

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T..49. NR..9 W..

-----Luce----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 8-9 -----

DESCRIPTION OF CORNER MONUMENT 2" Iron Pipe buried in N.-S. Firelane .

WITNESSES TO CORNER 10" Jackpine (1/4S-NBT) S 38° W 36 1/2 Links - - - -

10" Jackpine (1/4S NBT) N 55° E 18 Links - - - -

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Re-witnessed Corner as set by Marcus Schaaf, Reg. Surveyor. Found 2"  
Iron Pipe in place witnessed by Pits and Mounds. No evidence of original witnesses.

Corner lies in N.-S. Firelane and 80 Links South of County Road No. 412.

Shown by B. McTiver, District Forester.

Corner was re-witnessed May 29, 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler ----- DATE 12/4/58 -----  
REGISTERED LAND SURVEYOR