

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR. 9 W.

Luce COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 8, 9, 16 and 17.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 8" Jack Pine S 37 E 67 Links (S 16 NBT)

6" Jack Pine N 25 W 44 Links (S 8 NBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Surveyor. Found 2" Iron Pipe in place with Jack Pine B.T. bearing N 71 E, 58 Links.

Tree down and in poor condition, both faces plain, scribe marks obliterated.

Corner lies in intersection of N-S-E-W firelanes.

Shown by B. McTiver, District Forester.

Corner was placed and witnessed on 29 May 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6-2-59
REGISTERED LAND SURVEYOR