

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 9. W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 22 and 23 . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 1/2" brass cap . . .

WITNESSES TO CORNER 14" Yellow Birch S 50° E . . . 34 links . . .

9" Hemlock N 67° E . . . 34 links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from two probable Hemlock B.T.'s; remains of Hemlock stumps in proper position.

Squared Cedar post in place set by T. J. McClaren, McMillan.

Corner shown to us by Gerald Kutchera, Assistant District Forester.

Corner placed and witnessed August 15, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler . . . DATE 8/17/56
REGISTERED LAND SURVEYOR