

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 9 W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 23 and 26 . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . .

WITNESSES TO CORNER 10" Hemlock ----- N 15° W ----- 64 links -----

14" Soft Maple ----- S 43° W ----- 85 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set 1/4 Corner from one Maple tree (green) but rotted inside; scribed Cedar post in proper position, set by J. Cook, Newberry.

Corner shown to us by Gerald Kutchera, Assistant District Forester.

Corner placed and witnessed August 15, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles ----- DATE 8/17/56  
REGISTERED LAND SURVEYOR -----