

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N.R. 8,9W


Luce COUNTY

DESCRIPTION OF CORNER North 1/16 Corner between Sections 19-24

CORNER MONUMENT 1" x 48" Iron pipe and wood Post.

DATE MONUMENT PLACED AND WITNESSED 8-28-58

WITNESSES TO CORNER..... 9" W. Pine N31°W 15 links



13" W. Pine N39°E 70 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed on line and paid way bet. Sec. Cor. to north and quarter corner location to south.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

DATE 1-20-71

REGISTERED LAND SURVEYOR