

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 34-35

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED _____

WITNESSES TO CORNER..... 12" Jack Pine (½S NBT) N11°E 106.8'



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in wet marsh, on east margin of a small lake.

This corner replaced at scribed wood post, set by H. Lawrence, R.L.S.
Found a Jack Pine stub with both faces in good condition, bearing N10°W, 1.60 chains.

Corner found and placed with L. Rubick, Aide.

SURVEYOR'S SEAL

SIGNED Billy B. Buckler DATE 1-20-71
REGISTERED LAND SURVEYOR