

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Northwest 1/16 corner, Sec. 24

CORNER MONUMENT 1" x 8" iron pipe and wood post

DATE MONUMENT PLACED AND WITNESSED 8-28-58

WITNESSES TO CORNER..... 12" W. Pine S41°W 17 links



8" W. Pine N17°E 45 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed at intersection of lines, quartering the NW $\frac{1}{4}$  of Sec. 24, while making a sub-division survey of this section.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler DATE 1-21-71  
REGISTERED LAND SURVEYOR