Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



LAND CORNER RECORD

| DESCRIPTION OF CORNER West 1/16 Cor. bet. Secs. 22-27 | |
|--|------|
| • | UNTY |
| | |
| CORNER MONUMENT 1" pipe with 4" aluminum cap. | |
| DATE MONUMENT PLACED AND WITHESSED 9-14-70 | |
| WITHESSES TO CORNER 7" W. Pine (W 1/16 BT) S79°W 35.8" | |
| 9" R. Pine (W 1/16 BT) S18°W 39.0" | |
| <u> </u> | |
| CIRCLE CORNER REGISTERED | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. Sec. Cor. to west and $\frac{1}{4}$ Cor. to east. Cor. lies in south edge of a wet marsh.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 9-23-70

REGISTERED LAND SURVEYOR