

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. Secs. 27-28

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-4-70

WITNESSES TO CORNER..... 7" Jack Pine ($\frac{1}{4}$ S NBT) N62°E 18.2'



CIRCLE CORNER REGISTERED

Witnesses by H. Lawrence, R.L.S.

12" Jack Pine stub ($\frac{1}{4}$ S NBT) S73°E 35.3'

AND
10" W. Pine ($\frac{1}{4}$ S NBT) S37°W 26.2'

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by H. Lawrence, R.L.S.
Found wood post in place with new witnesses.
Found no evidence of original witnesses.
Cor. lies in a low, wet jack pine marsh.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 9-21-70
REGISTERED LAND SURVEYOR