

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 21-22-27-28

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 5-4-70

WITNESSES TO CORNER..... 12" W. Pine (\pm S NBT) S11 $^{\circ}$ E 19.4'



11" Y. Birch (NBT) S56 $^{\circ}$ E 14.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as placed by H. Lawrence, R.L.S. Found wood post and witnesses as marked by Mr. Lawrence.
Found wood post and witnesses as marked by Mr. Lawrence.
Found remains of a hemlock stump bottom, bearing N65 $^{\circ}$ E 16 links for a probable bearing tree.
Corner found by District IV Survey crew, while making partial retracement of this area.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler REGISTERED LAND SURVEYOR DATE 9-22-70