

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 .. NR. 9. W ..

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 15, 16, 21 and 22.

DESCRIPTION OF CORNER MONUMENT 2" Iron Pipe buried in intersection of  
firelane E-W-N.

WITNESSES TO CORNER 24" W. Pine S 72 W 25 Links (S 21 NPT) -----

18" W. Pine N 37 W 40<sup>1</sup> Links (S 16 NPT) -----

12" Red Pine N 58 E 101 Links (S 15 NPT) -----

-----  
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was re-witnessed as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe in place with Jack Pine S.T. S 51 W, 16 Links, in poor condition.

Shown by B. McTiver, District Forester.

Corner was placed and witnessed on 29 May 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 6-2-59  
REGISTERED LAND SURVEYOR