## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_49 NR\_2 M\_\_\_

	Luce COUNTY
DESCRIPTION OF CORNE	R 1/4 comer between Sections 15 and 21.
DESCRIPTION OF CORNER	R MONUMENT 2" Iron Pipe set in E-W firelane.
WITNESSES TO CORNER	8" Jack Pine _ N 20 E 48 Links (1/4 3 NPT)
	9" Jack Pine _ \$ 61 N _ 40 Links _ (1/4_8 IRT)

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe in place, witnessed by Pits and Mounds.

No evidence of original B.T. is.

Found 10" Jack Pine 3 37 E,  $17\frac{1}{2}$  Links, marked "1/4" by unknown surveyor.

Shown by P. McTiver, District Forester.

Corner was placed and witnessed on 29 May 1958.

SURVEYORS SEAL

SIGNED Billy D. Buchler DATE 6-3-59