

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 9 W. . . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 16, 17, 20 and 21.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap. -----

WITNESSES TO CORNER 10" Jack Pine S 49 W 31 Links (S 20 NET) -----

10" Jack Pine N 55 E 25 Links (S 16 NET) -----

11" Jack Pine N 30 W 65 Links (S 17 NET) -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe in place with Y. Pine B.T. N 27 E, 33 Links; this is a high stump, burned, and Jack Pine B.T. S 17 W, 44 Links, down and in poor condition.

Corner lies in intersection of E-W-S firelanes.

Shown by B. McTiver, District Forester.

Corner was placed and witnessed on 29 May 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6-2-59
REGISTERED LAND SURVEYOR