MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_49. NR_9.W__

		Luce	_ COUNTY
DESCRIPTION OF CO	DRNER 1/4 corner between Sect	ions 7 and 18.	
DESCRIPTION OF CO	RNER MONUMENT 1" Pipe with	h 4" Brass Cap.	
WITNESSES TO COR	NER _ 30" W. Pine _ N 30 E, 20	8 Links (1/4 S 187	·)
	26" Red Pine S 61 N, 7	3 Links (1/4 S MRT	2)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe in place with Tamarack stump bottom bearing S 14 E, 29 Links.

Corner lies at foot of steep slope.

Shown to us by B. McTiver, District Forester.

Corner was placed and witnessed on 28 May 1958.

SURVEYORS SEAL

Signed Billy D. Buckler DATE 6-4-

REGISTERED LAND SURVEYOR