CONS. 4047 4/86

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 49 NR 9W

		·		Luce	_ COUNTY
DESCRIPTION	OF CORNER	Section corner c	ommen to Section	as 7, 8, 17	and 18.
DESCRIPTION	OF CORNER	MONUMENT_1" P	ipe with 4" Bras	se Cap.	
WITNESSES	TO CORNER	8" Jack Pine	5 41 W 108½	Links, (§]	rą ńbł) –
		_8"_Jack Pine	N 70 W _ 54]	Links, (8_7	NBT)
					
				. -	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Serveyer.

Found 2" Iron Pipe in place with J. Pine B.T. N 19 E, 32 Links, down, burned, and Y. Pine S 14 W, 80 Links, stump bettem.

Corner lies in intersection of N-S-E-W firelanes.

Shewn by B. McTiver, District Ferester.

Corner was placed and witnessed on 28 May 1958.

SURVEYORS SEAL

Billy D. Buckler

GNED_____Billy D. Buckler DATE 6-