LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Luce	Located in:	Corner Code ##
_	(County)		•••••
1.	Public Land Survey	T .49# R 9¥	C3
		T B	
		T R	
		T R	
2.	Property Controlling	STT49#R_49#	1
	in Section	S T R	
3.	Miscellaneous	S T R	
_	Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____ . Recorded Plat

5. Private Claims

i, <u>Staphas J. Saveskosti</u>, in a field survey on <u>1988-73, 1887</u>, 19—, do hereby certify hat under requirements of P.A. 74, Michigan P.A. of 970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

2 3 3 2 3 3 4 35 36 11 12 3 1 3 2 3 3 3 3 3 3 4 3 5 3 6

A. Description of original monument and accessories and/or subsequent restoration:

(C3) Section corner common to sections 5-6-7-8. Corner previously recorded by Billy D. Buckler as remonumented in 1959 at a position determined by Marcus Schaaf, ca. 1920's, from original evidence. The corner was monumented with a 2" pipe and the following BBT's: 8" J.Pine, B70W 54.5 Links (S6 BBT), 7" J. Pine B34E 38.5 Links (S5 BBT).

[1-Sec. 4] West 1/16 corner between Sec. 4, 749M-R9W and Sec. 33, 759M-R9W. Corner previously recorded by Billy D. Buckler in 1971. Buckler's witnesses: 8" J. Pine Borth, 31.6"; 8" R. Pine 803W 106.0". Buckler placed a 1" pipe with 4" aluminum cap at the corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C3) Found 2"124" iron pipe cast in a 7"17" square concrete base at the surface of the intersection of firelanes S-S-S-W, at record bearing and distance from Buckler's MBTs. Lowered the monument so that the top of the pipe is 6" below the road surface. Scribed new top blaze "85" on J. Pine SE BBT, and placed measuring mails in both 1959 BBTs. Marked two new bearing trees, described below.

(1-Sec. 4) Found Buckler's monument and accessories as noted above. Buckler's B. Pine blazed overgrown. Scribing visible on the J. Pine. Corner is 8' north of the centerline of E-V firelane. Scribed top blaze "1/16" and placed measuring mails in Buckler's BT's and marked two new witness trees, as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

(C3) 2"224" iron pipe.
Blazed, scribed, and set measuring mails in the following new beazing trees:
12" J. Pine \$53E 63.37' "\$8 HBT"
10" J. Pine \$30W 49.65' "\$7 HBT"
Remeasured to the 1959 HBTs:
12" J. Pine #16E 25.56'
10" J. Pine #67W 35.75'
7" squared post adjacent to corner on

the east.

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

[1-Sec. 4] Found 1" pipe with 4"
Aluminum cap. Blazed, scribed, and
placed measuring nails in the following
new bearing trees:
12" J. Pine 843W 8.25' mrkd "1/16 BT"
13" J. Pine 834E 53.44' mrkd "1/16 BT"
Set measuring nails in the record BBTs:
11" J. Pine 803W 106.35' mrkd "1/16"
Placed 5" squared R. Pine post adjacent
to and south of the measument.

Signed by Stephen J. Szepholi

Date 10-15-92

Surveyor's Michigan License No. _____33986

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1943