

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR 9-10 W.

Luce COUNTY

DESCRIPTION OF CORNER Section Corner for Sections 7-18-12-13

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Jack Pine N68°W 66 Links
Marked "S12 NBT"

2" Jack Pine S52°W 46 1/2 Links
Marked "S13 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe in place.

Corner lies in Intersection of N-S-E-W Firelines.

Shown to us by B. McTiver, District Forester.

Corner placed and witnessed March 13, 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 12/5/58
REGISTERED LAND SURVEYOR