

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10 W. .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section Corner Common to Sections 10-11-14-15 ---

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap -----

WITNESSES TO CORNER -- 18" Cedar-(S11 NBT) N-43° E - 69 Links -----

13" Soft Maple (S15 NBT) - S. 74° W - 27 Links- -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Corner as set by Marcus Schaaf, Reg. Surveyor. Found 2" Iron Pipe with Yellow Birch B.T. N 29° W 15 Links in good condition, tree dead but still standing.

Corner shown to us by B. McTiver, District Forester.

Corner placed and witnessed May 27, 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED ----- Billy D. Buckler ----- DATE 12/8/58 -
REGISTERED LAND SURVEYOR