

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10 W..

Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 5 and 8.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 7" Jack Pine S 31 E 35 Links (1/4 S NBT)

9" Jack Pine N 16 E 15 Links (1/4 S NBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Surveyor. Found 2" Iron Pipe
in place with W. Pine B.T. bearing S 50 E, 65 Links. B.T. in poor condition.

Corner lies in North edge of E.-W. firelane.

Shown by B. MCTiver, District Forester.

Corner placed and witnessed on 6 June 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 5-28-59
REGISTERED LAND SURVEYOR