

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR 10 W.

Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 16 and 17.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 14" Red Pine N 43 W 99 Links (1/4 S NBT)

14" Red Pine S 43 E 89 Links (1/4 S NBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from W. Pine B.T. bearing N 43 E, 38 Links. Tree down and in very poor condition. Found evidence of digging at corner. Found 2" Iron Pipe laying on ground beside firelane.

Corner lies on N.-S. firelane.

Shown by B. McTiver, District Forester.

Corner placed and witnessed on 3 June 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler
Billy D. Buckler DATE 5-28-59
REGISTERED LAND SURVEYOR