

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10 W.

\_\_\_\_\_ Ince \_\_\_\_\_ COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 13 and 24.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 10" Jack Pine N 26 E 14 Links (1/4 S NBT)

10" Jack Pine S 23 E 27 Links (1/4 S NBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Surveyor.

Found 2" Iron Pipe on ground. Y. Pine stump S 20 W, 19 Links with part of notch.  
Found stump hole N 17 E, 19 Links, for probably W. Pine B.T.

Found no evidence of digging in ground.

Corner lies in E-W firelane.

Shown to us by B. McTiver, District Forester.

Corner was placed and witnessed on 28 May 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 6-8-59  
REGISTERED LAND SURVEYOR