

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N.R. 10W


Luce COUNTY

DESCRIPTION OF CORNER ½ Cor. bet. Sess. 21-22

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED _____

WITNESSES TO CORNER..... 15" Cedar (½S NBT) N60°W 20.4'



10" Cedar (½S NBT) N17°E 27.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as set by unknown surveyor. Found a 2" iron pipe in place with down cedar, bearing S4°W, 14 links. Tree is in fair condition. Corner lies 1 chain west of river and in swamp. Corner found and placed with L. Rubick, Aide.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 1-20-71