LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. Two corners.

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 49 N. ~~S.~~, R. 10 E. ~~W.~~	h-5 15-Sec.10
2. PROPERTY CONTROLLING IN SECTION 10	T. 49 N. ~~S.~~, R. 10 E. ~~W.~~	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 8/1?/ 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

h-5 ¼ Corner bet. Secs: 10-15, set by Geo. H. Cannon, D.S. 1854.
Bearings were:
Hemlock 20" N47°W 24 lks. and Balsam 8" S60°E 5 lks.

15-Sec.10 West 1/16 Corner, on South side Sec. 10.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

h-5 Corner re-established midway and on line bet. two Sec. Cors. Corner lies on North side of E-W firelane.

15-Sec.10 Corner established midway and on line bet. Sec. Cor. to West and ¼ Cor. to East. Corner lies in North rut of E-W firelane.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminium cap at both corners.

h-5 Net Bearings: 14" W. Pine S7°W 75.4' and 16" N. Maple S42°W 50.4'

15-Sec.10 Bearings: 12" W. Pine S16°E 14.3' and 14" W. Pine N15°W 6.2'

SIGNED BY Billy D. Buckler DATE 1/4/73

SURVEYOR'S MICHIGAN REGISTRATION NO. 8007 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY CHIEF OF SURVEY PARTY DATE

APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR DATE (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. ML M735
DOUBLEDAY BROS. & CO. KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS