

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10. R.

_____ Twp _____ COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 14 & 23 _____

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap _____

WITNESSES TO CORNER 12" Red Pine - S 87° E - 27 Links _____

12" Red Pine - N 82° E - 36 Links _____

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by B. McTiver, District Forester, of Newberry. Corner had been previously been located and perpetuated by Marcus Schaaf, Registered Land Surveyor. Remains of one original B.T. still in place, poor condition.

Corner was replaced and witnessed May 22, 1952.

SURVEYORS SEAL

SIGNED James C. Schaefer DATE 2/18/53
REGISTERED LAND SURVEYOR