

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10 W. . .

----- Luca ----- COUNTY

DESCRIPTION OF CORNER Section Corner Common to Sections 17-18-19-20 . . .

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap . . . . .

WITNESSES TO CORNER 12" Beech (S20 NBT) S 11° E 17 Links . . . . .

9" Beech (S18 NBT) N 73° W 36 Links . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Corner as set by Marcus Schaaf, Reg. Surveyor. Found 2" Iron Pipe in place. No evidence of original B.T.s.

Shown to us by B. McTiver, District Forester.

Corner placed and witnessed June 3, 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 12/5/58  
REGISTERED LAND SURVEYOR