

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10 W. .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Meander Corner between Sections 19-20 on North Side  
of Perch Lake

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap -----

WITNESSES TO CORNER 10" Red Pine (M.C. - NBT) - S 47° - E - 34½ Links -----

10" Jackpine (M.C. NBT) - N 62° W - 34½ Links -----  
-----  
-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced Meander Corner from Yellow Pine B.T. (Green) in good condition  
bearing N 10° W 31 Links and Jackpine stump bottom S 89° E 42 Links.

Corner shown to us by B. McTiver, District Forester.

Corner placed and witnessed June 3, 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler ----- DATE 12/5/58  
REGISTERED LAND SURVEYOR