

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10 W.

Luce

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 1-2-11-12

DESCRIPTION OF CORNER MONUMENT $1\frac{1}{2}$ " x 50" iron pipe 6" below surface

WITNESSES TO CORNER 9" Jackpine N 70° E 74 links
"S 1 NBT"

6" Jackpine S 16° E 62 links
"S 12 NBT"

6" Jackpine S 14° W 89½ links
"S 11 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from one jackpine B.T. bearing NW 45 links in good condition.

Corner lies in intersection of E-W fire lanes.
+ S,

Corner shown to us by B. McTiver, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 6/13/57
REGISTERED LAND SURVEYOR