

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10 W.

_____ Ince _____

_____ COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec. 's 3-4

DESCRIPTION OF CORNER MONUMENT 3/8" x 3/4" iron bar 6" below surface

WITNESSES TO CORNER

<u>7" Red Pine</u>	<u>N 32° W</u>	<u>95 links</u>
<u>20" Red Pine</u>	<u>"1/4 S NBT"</u>	<u>83 links</u>
	<u>S 55° E</u>	
	<u>"1/4 S NBT"</u>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner as perpetuated by Marcus Schaff, Reg. Surveyor.

Found 2" pipe in center of N-S fire line.

Found one jackpine B.T. in poor condition.

Also found NBT by H. Lawrence, Reg. Surveyor.

Corner shown to us by B. McTiver, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/12/57
REGISTERED LAND SURVEYOR