## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 48-49 NR 10 W

	Fire	COUNTY
DESCRIPTION OF CORNER	Section Corner common to Sec. 1s. 2-3-3	4 <u>-</u> 35
DESCRIPTION OF CORNER	MONUMENT_1" pipe with 4" brass cap	
WITNESSES TO CORNER	7" Tamarack S 54° E 75½	links
	10" W. Pine N 28° W 153\frac{1}{2}	links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from one spruce B.T. bearing S 66° E 16 links. B.T. in excellent condition.

Distance south to pond 1 ch.

Corner lies 12 chs. south of swamp edge and in wet marsh.

Corner perpetuated by Jim Cook, surveyor, in 1936.

Shown to us by B. McTiver, District Forester.

SURVEYORS SEAL