

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 .. NR. 10 W ..

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 2-3-10-11

DESCRIPTION OF CORNER MONUMENT Set 1" x 4' iron pipe buried 6" deep ..

WITNESSES TO CORNER 8" Jack pine .. N 63° W .. 103 links ..

"S 3 NBT"

8" Jack pine .. S 74° W .. 174 links ..

"S 10 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced corner from two jackpine B.T.s bearing S 25° E 99 links in
good condition (down), and S 23° W 162 links in poor condition.

Corner lies in intersection N-S-E-W fire lines.

Corner shown to us by B. McTiver, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 6/13/57
REGISTERED LAND SURVEYOR