CONS. 4047 4/56

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 49 NR 10 W

]	MCe		COUNTY	
DESCRIPTION OF CORNER	Meander corner between	a Sec.'a 2	-3 on shore	of Lake Superior	
DESCRIPTION OF CORNER	MONUMENT1"_pipe	with 4" b	rass_cap		
WITNESSES TO CORNER .	8 Twin Red Pine	s_32°	<u>w 61</u>	links	
	10" Red Pine	"Wat. BI"			
		W.C. BT			
		~			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed witness corner 2.50 chs. south of positionof meander corner.

Established this witness corner by chaining and extending section line from 1/4 corner between Sec. 1s 2-3 7.50 chs. south of here.

Gov't chainage = 10.00 chs. from 1/4 corner to meander corner.

Considerable erosion along lake shore.

Placed corner with B. McTiver, District Forester and Lawrence Rubick, Forestry Aide.

SURVEYORS SEAL