

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR. 10 W

_____ Ince _____ COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 2-11

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER	9" W. Pine	N 26° E	72 links
		"1/4 S NBT"	
	9" W. Pine	S 89° W	82 links
		"1/4 S NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner as perpetuated by Marcus Schaff, Reg. Surveyor.

2" iron pipe in place.

Found one jackpine B.T. bearing S 68° E 15 links (down) in good condition.

Also found jackpine B.T. for old effaced corner south and west of 1/4 corner.

1/4 corner lies on south edge of E-W fire lane.

Shown to us by B. McTiver, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/13/57
REGISTERED LAND SURVEYOR