## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 Luce Co. 2 Corners.

| FOR CORNERS OF -:  |  | LOCATED IN-:   | CORNER CODE NUMBER   |  |
|--|--|--|--|--|
| 1. PUBLI   | C LAND SURVEY  | _ T49 _ X., R10 _ W.   | H-11. G-10   |  |
| 2. PROPERTY CONTROLL- ING IN SECTION——, T. —— S., R. —— W. ———   |  |  |  |  |
| 3. MISCEI<br>PROPI   |  |  |  |  |
| 4. LOT N   | 0, RECO  | ORDED PLAT   |  |  |
| 5. PRIVA   | TE CLAIMS  |  |  | REGISTER OF DEEDS STAMP AND FILING NUMBER  |
| the corne<br>re-establis<br>and rules<br>Bureau of<br>and 5 abo<br>as express<br>Decree of   | r points mentioned in li-<br>shed, monumented, re-ra-<br>therefore as required in<br>a Land Management or<br>ove were, in a field surve-<br>sed below and in confor-<br>fa Court of law: | nes 1 and 2 above were, in a monumented, recovered or reduction the current manual of survive a decree of a court of law by on | field survey on 6-8 estored as expressed below and ey instructions of the United S . Furthermore, that the corner, 19, found, recovered, rest Michigan State Board of Registrations. | of P.A. 74, Michigan P.A. of 1970,  , 1978, established, in conformance with regulations tates Department of the Interior, points mentioned in lines 3, 4 ored, established or re-established ration for Land Surveyors or, by a mon D.S. in 1854.  South, 49 1ks.   |
| 0_10   | Quarter Corner<br>Bearings were:   | between Sections 27-<br>Beech 5, S20°E, 26   | 28, det by Geo. H. Car<br>lks. and Beech 10, S37   | non D.S. in 1854.<br><sup>O</sup> W, 14 lks.   |
| B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  H-11 Corner replaced from original bearing tree; a stump South 49 lks. Stump burned notch remains. Found wood post at corner. |  |  |  |  |
| <b>G-1</b> 0   | Corner restored evidence of ori  |  | sure between two Secti   | on Corners. Found no   |
|  | -  | corner and accessories estab   | lished to perpetuate locating the  | e position of the corner:  |
| F-11   | New Rearings:  | o<br>12" R. Pine. S28 W.   | 41.6' and 12" W. Pir<br>nedge of small island  | ne, N56 <sup>0</sup> W, 37.7'.<br>In open marsh.   |
| G-10   | New Bearings:  | 18" W. Pine, S30°E,  | 13.8' and 10" W. Pir   |  |
| SURVEY   | DITIA D' DUCE  | GISTRATION NO. 8887  | 7<br>1. DATE 9-8-78  | BILLY DE BILLY DE BUCKLER LAND SURVEYOR SEANOL SEAN |
| SIGNED   | BY   |  | DATE   |  |
| APPROVED AND SIGNED BY DATE DATE   |  |  |  |  |
|  |  | MICHIGAN REGISTERED L  | AND SURVEYOR   | (GEAL)   |
|  |  |  |  |  |

SURVEYOR'S MICHIGAN REGISTRATION NO.\_\_\_\_\_