

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR. 11W

_____ Ince _____ COUNTY

DESCRIPTION OF CORNER _____ 1/4 cor. between secs: 14-23 _____

DESCRIPTION OF CORNER MONUMENT _____ 2" Iron Pipe buried in Firelane _____

WITNESSES TO CORNER _____ 12" W. Pine (1/4s NBT) N30° W 21½ Lks. _____

_____ 13" R. Pine (1/4s NBT) S53° W 24 Lks. _____

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed 1/4 cor. as set by Marcus Schaaf, Reg. Surveyor.
Found Iron Pipe in place with two W. Pine B.Ts. Bearing N38° W
16 Lks. and S41° W 22 Lks. both in poor condition. Cor. lies
in intersection of firelanes E-W-S. Cor. wit. 6/23/59 with
R. Norkoli, D.F.

SURVEYORS SEAL

SIGNED _____ *Billy D. Buckler* _____
Billy D. Buckler DATE 8/5/59
REGISTERED LAND SURVEYOR