

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 11. W

Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 21 and 28

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 13" Red Pine (1/4s NBT) N 72° E 81 Links

2" Jack Pine (1/4s NBT) S 18° W 34 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. This corner was replaced as set by Marcus Schaeff, Registered Surveyor. Found 2" Iron Pipe in place. Found Pine stump S 44° W 11 Links and down Jack Pine N 37° E 30 Links, both faces in poor condition.

Found Old H. T.s, Pine S 27° E 10 Links and N 10° W 53 Links. Both stumps in poor condition. These stumps are from the original survey and later defaced.

Corner lies in intersection of N E W fire lanes.

Corner was placed and witnessed June 17, 1958.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/29/60