

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR. 11 W

L u c e COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 15, 16, 21, 22

DESCRIPTION OF CORNER MONUMENT 2" Pipe buried in intersection of firelanes.

WITNESSES TO CORNER 18" Red Pine (S 15 NBT) N 30° E 56 Links

8" Red Pine (S 21 NBT) S 70° W 44 1/2 Links

7" Red Pine (S 22 NBT) S 47° E 45 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced at intersection of firelines in all four directions. Found Iron Pipe laying beside firelane, apparently removed by traffic.

Corner was placed and witnessed July 21, 1960 with L. Rubick, Aide.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 9/14/60