MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.49 NR 11 W

	-	Ţ <i>ū</i> 'c'e'	COUNT	⁻ Y
DESCRIPTION OF CORNER	1/4 corner betw	een_Sections 22_a	ind 27	
DESCRIPTION OF CORNER	MONUMENT	2" Iron Pipe		
WITNESSES TO CORNER .	6" Red Pine	(1/4s NBT)	S 43° E 74 1/2 Link	8
	8" Jack Pine	(1/4s NBT)	N 54° W 43 Links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-witnessed as set by Marcus Schaaf, Registered Surveyor. Found Iron pipe in place with two original B.T.'s in proper position. Corner lies in e-w firelane.

Corner was placed and witnessed July 21, 1960 with L. Rubkck, Aide.

SURVEYORS SEAL

SIGNED SILLY Suchles DATE 9/14/60
RÉGISTERED LAND SURVEYOR

RÉGISTERED LAND SURVEYOR