

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between sections 19-30.

CORNER MONUMENT 1" pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 10-23-62

WITNESSES TO CORNER..... 7" Jack pine ( $\frac{1}{4}$ S NBT) S45°W, 31 $\frac{1}{2}$  links



6" Red Pine ( $\frac{1}{4}$ S NBT) N60°E, 37 links

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner was replaced from two W. Pine stumps bearing S45°E, 12 links and N8°W, 19 links. Found 2" iron pipe 2 links west of corner.

Corner lies in intersection of fire lanes N-E-W.

**SURVEYOR'S SEAL**

SIGNED Billy D. Buckler DATE July 19, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler