

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N.R. 11-12W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 19-24

CORNER MONUMENT 1 1/2" iron pipe buried in intersection of five lanes E-S-E-

DATE MONUMENT PLACED AND WITNESSED 10-23-62

WITNESSES TO CORNER..... 10" Red Pine (1/4 SNBT) N48°E, 23 links



7" Jack Pine (1/4 SNBT) S25°E, 33 1/2 links

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

Corner witnessed as set by Marcus Schaaf, registered land surveyor. One original B.T. in place, a W. line stub N57°E, 22 links. Both faces in good condition.

Corner witnessed with R. Norkoli, Dist. Forester.

**SURVEYOR'S SEAL**

SIGNED Billy D. Buckler DATE July 19, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler