

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. Secs. 7 and 8.

CORNER MONUMENT 2" Iron pipe.

DATE MONUMENT PLACED AND WITNESSED 7-7-63

WITNESSES TO CORNER..... 7" Jack Pine ($\frac{1}{4}$ S. N.B.T.) N. 21° W., 59 lks.



8" Jack Pine ($\frac{1}{4}$ S. N.B.T.) S. 81° W., 33 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-witnessed as set by Marcus Schaaf, Registered
Land Surveyor.

Corner lies in N.-S. Fire lane.

Found no evidence of original Cor.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1/27/64
REGISTERED LAND SURVEYOR