

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 24-25

CORNER MONUMENT 1" pipe with 4" aluminum cap (buried)

DATE MONUMENT PLACED AND WITNESSED 8-1-62

WITNESSES TO CORNER..... 6" Jackpine (1/4 S NBT) S33°E 29 links



8" Jackpine (1/4 S NBT) N53°E, 47 1/2 links

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner was replaced at Iron Pipe set by Marcus Schaap, registered land surveyor.  
Corner lies in intersection of firelanes E-W-N-S.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963  
REGISTERED LAND SURVEYOR

Billy D. Buckler