

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER  $\frac{1}{4}$  corner between sections 23-26

CORNER MONUMENT 2" iron pipe buried in firelane.

DATE MONUMENT PLACED AND WITNESSED 8-1-62

WITNESSES TO CORNER..... 12" red pine ( $\frac{1}{4}$ S NBT) N35°E, 37 links



12" red pine ( $\frac{1}{4}$ S NBT) S16°E, 37 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by Marcus Schaaf, registered land surveyor.  
Corner lies in intersection of firelanes N-S-E-W.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE March 7, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler