

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR. 11 W.

Luce

COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 25-36

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

<u>15" Red Pine</u>	<u>N 80° W</u>	<u>162 links</u>
	<u>"1/4 S NBT"</u>	
<u>5" Jackpine</u>	<u>S 2° E</u>	<u>16 links</u>
	<u>"1/4 S NBT"</u>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner as set by Marcus Schaff, Reg. Surveyor.

Found 2" iron pipe in concrete.

Found two yellow pine B.T.s S 30° W 30 links and N 65° E 39 links in poor condition.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 6/25/57